

**Notice of deletion of UL certification display of our Motor Circuit Breakers due to non-compliance with UL certification of PA resin manufactured by Toyobo Co., Ltd.**

Toyobo Co., Ltd. has discovered that some of the UL-certified performance values of the company's PA resin "GLAMIDE ™" do not conform. It was announced that UL certification will be revoked on February 3, 2021. For details, please refer to the announcement by Toyobo Co., Ltd.  
[https://www.toyobo-global.com/system/files/202102/node\\_327/press\\_20210203\\_1\\_e.pdf](https://www.toyobo-global.com/system/files/202102/node_327/press_20210203_1_e.pdf)

We report the impact on our Motor circuit breakers and its response as follows.

1. Impact and response on our products

Due to the cancellation of UL certification of Toyobo Co., Ltd. "GLAMIDE ™", the UL certification label of the motor circuit breaker using that material will be deleted.

There are no problems with safety or performance of products that have already been shipped. UL certification is also valid.

2. Products

Model : Motor circuit breakers  
Type : MMP-T32, MMP-T32BC

Note: Due to the deletion of the UL certification display above, if a manual motor starter without the UL certification display is used, the UL certification of the Type E / Type F combination motor controller and group installation will also be invalidated.

In addition, there is no effect on UL-certified motor starters and various options.







3. Effective date

Production from April, 2021

Issue date: March, 2021	<b>MITSUBISHI ELECTRIC CORPORATION</b> <b>NAGOYA WORKS, KANI FACTORY</b> 3-5 HIMEGAOKA KANI CITY GIFU PREF. 509-0249 JAPAN TEL. +81-574-61-1952, FAX. +81-574-63-1208
Title: Notice of deletion of UL certification display of our Motor Circuit Breakers due to non-compliance with UL certification of PA resin manufactured by Toyobo Co., Ltd.	

4. Change points

Removes the UL certification mark and associated information from the part and the products that use it. "NO UL" mark is displayed on the top surface of the individual box. (Until March 2022 production, scheduled to be deleted after April the following year)

	Before (With UL certification mark)	After (Without UL certification mark)
Left side of product		
Right side of product		
Top surface of individual box		

<p>Issue date: March, 2021</p> <p>Title: Notice of deletion of UL certification display of our Motor Circuit Breakers due to non-compliance with UL certification of PA resin manufactured by Toyobo Co., Ltd.</p>	<p><b>MITSUBISHI ELECTRIC CORPORATION</b>  <b>NAGOYA WORKS, KANI FACTORY</b>          3-5 HIMEGAOKA KANI CITY GIFU PREF. 509-0249 JAPAN          TEL. +81-574-61-1952, FAX. +81-574-63-1208</p>
--	---