

Notice of deletion of UL certification mark of auxiliary contact blocks and related products

As announced in FOR IMMEDIATE RELEASE (No.3411), the specification will be changed because a resin material used in our products is different from the material certified and registered by Underwriters Laboratories (UL).

The UL certification mark (UL Recognition and UL Listing) will be deleted, and we report the changes and response as follows.

1. Products

- (1)Auxiliary Contact Block: UT-AX2, UT-AX4
- (2)Contactor Relay: SR-T9, SRD-T9
- (3)Reversing Magnetic Contactor: S-2×T32, SD-2×T32

-Note: The specification changes also apply to some types with suffixes, "BC" and etc. (excluding "SQ")

2. Points to be changed

The UL certification mark on the products is deleted.

-Note: Refer to Appendix 1 for the details.

3. Reason for the modification

The UL certification mark is deleted because a resin material used in UT-AX4 and UT-AX2 is different from the material certified and registered by UL.

4. Distinction of products

- (a) Appearance
(Confirmation of the UL certification mark of the product)
-Note: Refer to Appendix 1.
- (b) Confirmation of the identification mark "R" on the packing label
-Note: Refer to the figure on the right for the display position of the mark.










Fig. packing label (typical examples)



5. Effective date

Immediately

<p>Issue date: May, 2021</p> <p>Title: Notice of deletion of UL certification mark of auxiliary contact blocks and related products</p>	<p>MITSUBISHI ELECTRIC CORPORATION NAGOYA WORKS, KANI FACTORY 3-5 HIMEGAOKA KANI CITY GIFU PREF. 509-0249 JAPAN TEL. +81-574-61-1952, FAX. +81-574-63-1208</p>
---	---

(Appendix 1)

Type	Changes	Before (With UL certification label)	After (No UL certification label)
UT-AX2 UT-AX4	deletion of the UR mark on the side of the auxiliary contact unit		
SR-T9 SRD-T9	deletion of UL mark on relay body		
S-2xT32 SD-2xT32	deletion of the UR mark on the side of the auxiliary contact unit (※1)		

- ※1. Due to the deletion of the UR mark on the UT-AX4, the S-2 x T32 and SD-2 x T32 shipped from us are not UL certified products. The part of magnetic contactor (S-T32 and SD-T32) excluding the auxiliary contact unit is UL certified product.
- ※2. The contents displayed in the above figure are typical examples.
- ※3. Auxiliary contact blocks (UT-AX2 and UT-AX4) cannot be used alone, but can be used in combination with a magnetic contactor or a contactor relay, so they are UL Component certification (). Magnetic contactors and contactor relays can be used alone, they are UL product certification ()

Issue date: May, 2021	MITSUBISHI ELECTRIC CORPORATION NAGOYA WORKS, KANI FACTORY 3-5 HIMEGAOKA KANI CITY Gifu PREF. 509-0249 JAPAN TEL. +81-574-61-1952, FAX. +81-574-63-1208
Title: Notice of deletion of UL certification mark of auxiliary contact blocks and related products	