

Sales and Service

UL Certification Withdrawal for Mitsubishi Electric Motor Circuit Breakers and Effect on Combinations with Mitsubishi Electric AC Servos

Thank you for your continued patronage of the Mitsubishi Electric AC servo system. Withdrawal of UL certification for the MMP-T32 series motor circuit breakers (Type E combination motor controllers) affects some combinations of the MMP-T32 series and Mitsubishi Electric AC servos.

1. Target Model





MR-J5 series, MR-J4 series, MR-JET series, and MR-JE series
(3-phase 200 to 240 V AC: 5 kW or less, 3-phase 380 to 480 V AC: 7 kW or less)

2. Details

Combinations of the UL-marked MMP-T32 series on the market or in use and the AC servos can be used safely, and the performance is ensured.

Note that combinations of the MMP-T32 series without UL marking (manufactured in April 2021 or later) and the AC servos do not meet UL requirements.

Table 1. Identification of UL certification marking (MMP-T32 series)

| | With UL marking | Without UL marking |
|----------------------------------|---|---|
| Left side of the product |  |  |
| Top surface of the packaging box |  |  |

| | | | | |
|----------------------|---------------|--------------|--|--|
| Date of issue | December 2021 | Title | UL Certification Withdrawal for Mitsubishi Electric Motor Circuit Breakers and Effect on Combinations with Mitsubishi Electric AC Servos | Mitsubishi Electric Corp., Nagoya Works 1-14, Yada-minami 5-chome, Higashi-ku, Nagoya 461-8670 Tel.: +81 (52) 721-2111 Main line |
|----------------------|---------------|--------------|--|--|