

UL File Number Change for Sensorless Servo Drive Units

Thank you for your continued patronage of Mitsubishi Electric drive control products.
The UL file number of sensorless servo drive units will be changed.

1. Products Affected

All UL-listed sensorless servo drive units

2. Details of the Change

The UL file number assigned by UL will be changed as shown in Table 1. If the UL file number of Mitsubishi Electric Corporation is indicated in your factory inspection procedure (UL procedure), Instruction Manuals, and other documents, refer to the new UL file number or overwrite the UL file number to the new number.

This number change does not affect the appearance and specifications of the products.

Table 1: Current and new UL file numbers

	Current	New
File No.	E131592	E113619

3. Date of Change

The UL file number will be changed on December 1, 2020.

The change will be reflected on the web page of UL, where the UL file numbers can be searched, after about one week.

Reference

UL Product iQ™ (UL product search web page)

<https://iq.ulprospector.com/en/>

Date of issue	November 2020	Title	UL File Number Change for Sensorless Servo Drive Units	Mitsubishi Electric Corp., Nagoya Works 5-1-14 Yada-minami, Higashi-ku, Nagoya 461-8670 Tel.: +81 (52) 721-2111 Main line
----------------------	---------------	--------------	--	---