

Appearance Change of the Screw of the FR-BFP2 Series Inverter Option

Thank you for your continued patronage of Mitsubishi Electric drive control products.
The appearance of the screw enclosed with the FR-BFP2 series inverter option will be changed.

1. Products Affected


FR-BFP2 series

2. Details of Change


The appearance (color) of the enclosed screw for leakage current countermeasure will be changed.
The change does not affect the quality, performance, or specifications of the products.

◆ Insertion position of the screw for leakage current countermeasure

When the Filterpack is used, leakage current can be reduced by removing the earth (ground) cable of the capacitive filter and fixing the cable with the plastic screw and the plastic spacer.



◆ Appearance of the screw for leakage current countermeasure

Before	After
 White	 Milky white

3. Date of Change

The change will be sequentially applied to products manufactured in July 2023 or later.

Date of issue	June 2023	Title	Appearance Change of the Screw of the FR-BFP2 Series Inverter Option	Mitsubishi Electric Corp., Nagoya Works 5-1-14 Yada-minami, Higashi-ku, Nagoya 461-8670 Tel.: +81 (52) 721-2111 Main line
----------------------	-----------	--------------	--	---

4. Product Identification

The SERIAL (determined by date of production) can be checked on the rating plate of the FR-BFP2.

SERIAL example on rating plate
□ 03 Z 000
Symbol Year Month Control number

SERIAL

The SERIAL consists of one symbol, three characters indicating the production year and month, and three characters indicating the control number.

The last digit of the production year is indicated as the Year, and the Month is indicated by 1 to 9, X (October), Y (November), or Z (December).