

Sales and Service

Change in Appearance of External Input Connectors of FX5-nSSC-S, LD77MS, QD77GF, and Q170MSCPU

Thank you for your continued patronage of the Mitsubishi Electric AC servo system. The appearance of the external input connectors of FX5-nSSC-S, LD77MS, QD77GF, and Q170MSCPU will be changed.

1. Target Model


FX5-nSSC-S, LD77MS, QD77GF, Q170MSCPU, and their derived models

2. Reason for the Change

To improve the obtainability of the parts

3. Details of the Change

The external input connectors will have tapped holes instead of lock nuts. This change does not affect the functions and performance of the product. The recommended connector set LD77MHIOCON will fit into the changed connectors properly.



4. Schedule

This change will be made sequentially from the May 2020 production.

Note that, depending on the stock status, the products with both the former and new appearances may be distributed in the market around the same time.

Date of issue	March 2020	Title	Change in Appearance of External Input Connectors of FX5-nSSC-S, LD77MS, QD77GF, and Q170MSCPU	Mitsubishi Electric Corp., Nagoya Works 1-14, Yada-minami 5-chome, Higashi-ku, Nagoya 461-8670 Tel.: +81 (52) 721-2111 Main line
----------------------	------------	--------------	--	---