

Sales and Service

Appearance Change in the RD78G CC-Link IE TSN Connector and Back Plate

Thank you for your continued patronage of the Mitsubishi Electric AC servo system. The appearance of the CC-Link IE TSN connector and back plate of the product will be changed and the CC-Link IE TSN connector cover will be removed.

1. Target Model

RD78G4, RD78G8, RD78G16, RD78G32, and RD78G64

* Products derived from the models above are also subject to change.





2. Reason for the Change

To improve the obtainability of the parts

3. Details of the Change

- (1) The appearance of CC-Link IE TSN connectors on the front of the products will be changed (improvement in the brightness of the red LED and change in the shell shape).
- (2) The cover of the above connector will be removed.
- (3) The back plate shape will be changed.

* This change does not affect the functions and performance of the products.

Parts to be changed	Before change	After change
(Front) CC-Link IE TSN connectors		(1) Improvement in the brightness of the red LED  (1) Change in the shell shape (2) No connector cover
(Back) Plates		

4. Schedule

This change will be made sequentially from the June 2021 production.

Note that, depending on the stock status, the products with both the former and new appearances may be distributed in the market around the same time.

Date of issue	April 2021	Title	Appearance Change in the RD78G CC-Link IE TSN Connector and Back Plate	Mitsubishi Electric Corp., Nagoya Works 1-14, Yada-minami 5-chome, Higashi-ku, Nagoya 461-8670 Tel.: +81 (52) 721-2111 Main line
----------------------	------------	--------------	--	--