



## Production Discontinuation of GOT-F900 series and A950 Handy GOT

■Date of Issue

March 2024

■Relevant Models

GOT-F900 Series, A950 Handy GOT

Thank you for your continued support of Mitsubishi Electric Graphic Operation Terminal (GOT).

We would like to announce that we will discontinue production of the long appreciated GOT-F900 series and A950 Handy GOT as follows.

### CONTENTS

1	Models to be discontinued/discontinuation schedule	2
1.1	Main GOT units	2
1.2	Options	2
1.3	Software	3
2	Reason for production discontinuation	3
3	Alternative models	4
3.1	Main GOT units	4
3.2	Options	5
3.3	Software	5
4	Others	6
4.1	Repair acceptance period after discontinuation	6
4.2	Spare parts after Production Discontinuation	6
	Revisions	6

GOT-A-0222-A

## 1 Models to be discontinued/discontinuation schedule

### 1.1 Main GOT units

Models to be discontinued		Order acceptance	Production discontinuation	Repair acceptance
Product	Model			
F940WGOT	F940WGOT-TWD F940WGOT-TWD-E F940WGOT-TWD-C	Through March 31, 2011	From March 31, 2011	Through March 31, 2018
F940GOT	F940GOT-SWD F940GOT-SWD-E F940GOT-SWD-C	Through March 31, 2011	From March 31, 2011	Through March 31, 2018
	F940GOT-LWD F940GOT-LWD-E F940GOT-LWD-C			
F943GOT	F943GOT-SWD			
	F943GOT-LWD			
F930GOT	F930GOT-BWD F930GOT-BWD-E F930GOT-BWD-C F930GOT-BWD-T	Through March 31, 2011	From March 31, 2011	Through March 31, 2018
	F933GOT-BWD			
F930GOT-K	F930GOT-BBD-K F930GOT-BBD-K-E F930GOT-BBD-K-C	Through March 31, 2011	From March 31, 2011	Through March 31, 2018
F920GOT-K	F920GOT-BBD-K F920GOT-BBD-K-E F920GOT-BBD-K-C	Through March 31, 2011	From March 31, 2011	Through March 31, 2018
	F920GOT-BBD5-K F920GOT-BBD5-K-E F920GOT-BBD5-K-C			
F940 Handy GOT	F940GOT-SBD-H F940GOT-SBD-H-E	Through March 31, 2011	From March 31, 2011	Through March 31, 2018
	F940GOT-LBD-H F940GOT-LBD-H-E			
F943 Handy GOT	F943GOT-SBD-H F943GOT-SBD-H-E			
	F943GOT-LBD-H F943GOT-LBD-H-E			
F940 Handy GOT RH type	F940GOT-SBD-RH F940GOT-SBD-RH-E	Through March 31, 2011	From March 31, 2011	Through March 31, 2018
	F940GOT-LBD-RH F940GOT-LBD-RH-E			
F943 Handy GOT RH type	F943GOT-SBD-RH F943GOT-SBD-RH-E			
	F943GOT-LBD-RH F943GOT-LBD-RH-E			
A950 Handy GOT	A950GOT-SBD-M3-H	Through March 31, 2011	From March 31, 2011	Through March 31, 2018
	A950GOT-LBD-M3-H			
A953 Handy GOT	A953GOT-SBD-M3-H			
	A953GOT-LBD-M3-H			

### 1.2 Options

Models to be discontinued		Order acceptance	Production discontinuation	Repair acceptance
Product	Model			
Screen data transfer board	F9GT-40FMB	Through March 31, 2011	From March 31, 2011	Through March 31, 2018
	F9GT-40UMB			

GOT-A-0222-A

Models to be discontinued		Order acceptance	Production discontinuation	Repair acceptance
Product	Model			
EPROM memory	FX-EPROM-4M	Through March 31, 2011	From March 31, 2011	Through March 31, 2018
GOT ⇔ PLC connection cable (F9GT-HCNB ⇔ PLC when Handy GOT is used)	FX-40DU-CAB	Through March 31, 2011	From March 31, 2011	Not applicable
	FX-40DU-CAB-10M			
	FX-40DU-CAB-20M			
	FX-40DU-CAB-30M			
	FX-50DU-CAB0			
	FX-50DU-CAB0-1M			
	FX-50DU-CAB0-10M			
	FX-50DU-CAB0-20M			
	FX-50DU-CAB0-30M			
	FX-50DU-CAB0L			
	FX-50DU-CABL			
	FX-40DU-CAB/EN			
	FX-50DU-CAB0/EN			
External connection cable (Handy GOT exclusive)	F9GT-HCAB-3M	Through March 31, 2011	From March 31, 2011	Not applicable
	F9GT-HCAB-10M			
	F9GT-HCAB1-3M			
	F9GT-HCAB1-10M			
	F9GT-RHCAB-3M			
	F9GT-RHCAB-6M			
	F9GT-RHCAB-10M			
	F9GT-RHCAB1-3M			
	F9GT-RHCAB1-10M			
GOT ⇔ PLC connection relay cable (Handy GOT exclusive)	F9GT-HCAB2-150	Through March 31, 2011	From March 31, 2011	Not applicable
	F9GT-HCAB3-150			
	F9GT-HCAB5-150			
	F9GT-RHCAB2-150			
	F9GT-RHCAB3-150			
	F9GT-RHCAB5-150			
Connector conversion box (Handy GOT exclusive)	F9GT-HCNB	Through March 31, 2011	From March 31, 2011	Through March 31, 2018
Battery	PM-20BL <sup>*1</sup>	Through August 31, 2021	From September 30, 2021	Not applicable
	FX2NC-32BL <sup>*2</sup>	Through July 31, 2025	From October 31, 2025	

\*1 Start of made-to-order service: March 31, 2021

\*2 Start of made-to-order service: January 31, 2025

### 1.3 Software

Models to be discontinued		Order acceptance	Production discontinuation
Product	Model		
FX-PCS-DU/WIN	SW0PC-FXDU/WIN-E	Through March 31, 2011	From March 31, 2011

## 2 Reason for production discontinuation

Along with finer design rules and growing environmental awareness in recent years, we have difficulty in continuously procuring some main electronic parts of the GOT, such as semiconductor parts (microcomputers, memories, and ASICs). For the GOT-F900 series and A950 Handy GOT, we have continued the production by taking actions, such as stocking adequate discontinued parts. Nonetheless, we are about to run out of the parts and have difficulty in maintaining the production and quality systems.

GOT-A-0222-A

### 3 Alternative models

For alternative models to the GOT-F900 series and A950 Handy GOT, we recommend models with the fewest restrictions on their specifications.

However, depending on the application of your system, a model other than the ones recommended may be selected. Please check the specifications of your existing system and select a suitable model.

When replacing the models, refer to the following.

- Replacement Guidance (JY997D39301)
- Precautions when Replacing GOT-F900 Series, ET-940 Series, or A950 Handy GOT with GOT2000 Series for Japanese Market (GOT-A-0128)

#### 3.1 Main GOT units

GOT-F900 series, A950 Handy GOT in use		GOT1000 series recommended for replacement
F940WGOT	F940WGOT-TWD F940WGOT-TWD-E F940WGOT-TWD-C	GT1455-QTBD <sup>*1</sup> or GT1655-VTBD <sup>*1</sup>
F940GOT	F940GOT-SWD F940GOT-SWD-E F940GOT-SWD-C	GT1055-QSBD
	F940GOT-LWD F940GOT-LWD-E F940GOT-LWD-C	GT1050-QBBD
F943GOT	F943GOT-SWD	GT1055-QSBD
	F943GOT-LWD	GT1050-QBBD
F930GOT	F930GOT-BWD F930GOT-BWD-E F930GOT-BWD-C F930GOT-BWD-T	GT1030-HWDW
	F933GOT-BWD	GT1030-HWDW2
F930GOT-K	F930GOT-BBD-K F930GOT-BBD-K-E F930GOT-BBD-K-C	GT1040-QBBD
F920GOT-K	F920GOT-BBD-K F920GOT-BBD-K-E F920GOT-BBD-K-C	GT1030-HBDW
	F920GOT-BBD5-K F920GOT-BBD5-K-E F920GOT-BBD5-K-C	GT1030-HBLW
F940 Handy GOT	F940GOT-SBD-H F940GOT-SBD-H-E	GT1155HS-QSBD
	F940GOT-LBD-H F940GOT-LBD-H-E	GT1150HS-QLBD
F943 Handy GOT	F943GOT-SBD-H F943GOT-SBD-H-E	GT1155HS-QSBD
	F943GOT-LBD-H F943GOT-LBD-H-E	GT1150HS-QLBD
F940 Handy GOT RH type	F940GOT-SBD-RH F940GOT-SBD-RH-E	GT1155HS-QSBD
	F940GOT-LBD-RH F940GOT-LBD-RH-E	GT1150HS-QLBD
F943 Handy GOT RH type	F943GOT-SBD-RH F943GOT-SBD-RH-E	GT1155HS-QSBD
	F943GOT-LBD-RH F943GOT-LBD-RH-E	GT1150HS-QLBD
A950 Handy GOT	A950GOT-SBD-M3-H	GT1155HS-QSBD
	A950GOT-LBD-M3-H	GT1150HS-QLBD

GOT-A-0222-A

GOT-F900 series, A950 Handy GOT in use		GOT1000 series recommended for replacement
A953 Handy GOT	A953GOT-SBD-M3-H	GT1155HS-QSBD
	A953GOT-LBD-M3-H	GT1150HS-QLBD

\*1 When replacing the F940WGOT with GT1455 or GT1655, use either of the following attachments.

Model	Description	
GT15-50ATT-95W	Attachment for 5.7-inch models	F940WGOT → GT1455-QTBD
		F940WGOT → GT1655-VTBD

- The attachment can be used when the installation panel thickness is 1.2 to 3 mm.
- If the GOT is replaced with one with the attachment, the GOT will not comply with the ingress protection standards IP65f, IP67f, and NEMA4.

### 3.2 Options

Option in use	GOT1000 series recommended for replacement	
GOT ⇔ PLC connection cable (F9GT-HCNB ⇔ PLC when Handy GOT is used)	FX-40DU-CAB	GT01-C30R4-25P
	FX-40DU-CAB-10M	GT01-C100R4-25P
	FX-40DU-CAB-20M	GT01-C200R4-25P
	FX-40DU-CAB-30M	GT01-C300R4-25P
	FX-50DU-CAB0	GT01-C30R4-8P
	FX-50DU-CAB0-1M	GT01-C10R4-8P
	FX-50DU-CAB0-10M	GT01-C100R4-8P
	FX-50DU-CAB0-20M	GT01-C200R4-8P
	FX-50DU-CAB0-30M	GT01-C300R4-8P
	FX-50DU-CAB0L	There is no recommended replacement model.
	FX-50DU-CABL	There is no recommended replacement model.
	FX-40DU-CAB/BN	GT01-C30R4-25P
	FX-50DU-CAB0/BN	GT01-C30R4-8P
Screen data transfer board	F9GT-40FMB	GT10-50FMB (For GT105□, GT104□)
	F9GT-40UMB	
EPROM memory	FX-EPROM-4M	CF card (For GT115□(HS), GT1555)
External connection cable (Handy GOT exclusive)	F9GT-HCAB-3M	GT11H-C30-37P
	F9GT-HCAB-10M	GT11H-C100-37P
	F9GT-HCAB1-3M	GT11H-C30
	F9GT-HCAB1-10M	GT11H-C100
	F9GT-RHCAB-3M	GT11H-C30-37P
	F9GT-RHCAB-6M	GT11H-C60-37P
	F9GT-RHCAB-10M	GT11H-C100-37P
	F9GT-RHCAB1-3M	GT11H-C30
	F9GT-RHCAB1-10M	GT11H-C100
GOT ⇔ PLC connection relay cable (Handy GOT exclusive)	F9GT-HCAB2-150	GT11H-C15R4-8P
	F9GT-HCAB3-150	GT11H-C15R4-25P
	F9GT-HCAB5-150	GT11H-C15R2-6P
	F9GT-RHCAB2-150	GT11H-C15R4-8P
	F9GT-RHCAB3-150	GT11H-C15R4-25P
	F9GT-RHCAB5-150	GT11H-C15R2-6P
Connector conversion box (Handy GOT exclusive)	F9GT-HCNB	GT11H-CNB-37S

### 3.3 Software

Software in use	Alternative model
FX-PCS-DU/WIN	SW0PC-FXDU/WIN-E
	SW1DND-GTWK3-E

GOT-A-0222-A

## 4 Others

### 4.1 Repair acceptance period after discontinuation

We will provide repair services for the relevant products for seven years after the discontinuation of production.

However, please note that there may be cases where repairs cannot be performed if replacement parts become unavailable, regardless of the repair acceptance period.

Cables and batteries are not eligible for repair.

### 4.2 Spare parts after Production Discontinuation

You can purchase the following options as spare parts from Mitsubishi Electric System & Service Co., Ltd. after production discontinuation until the end of the repair acceptance period.

Product	Model	Remarks
Screen protector	F9WGT-40PSC	For F940WGOT
	F9GT-40PSC	For F940GOT, F940/A950 Handy GOT
	F9GT-30PSC	For F930GOT
Backlight	F9GT-40LTS	For F940GOT
	F9GT-30LTB	For F930GOT (except F930GOT-K)

### Revisions

Version	Issue date	Revision
A	March 2024	First edition