

[Issue No.] HIME-T-P-0143

[Title] CF Card Connector Change (GT1150, GT1155, GT1665HS series)

[Date of Issue] December 2014 (Ver. B: January 2016)

[Relevant Models] GT1155-QTBD, GT1155-QSBD, GT1150-QLBD, GT1155HS-QSBD,
GT1150HS-QLBD, GT1665HS-VTBD







Thank you for your continued support of Mitsubishi Graphic Operation Terminals (GOT).

Regarding some GOT1000 series models, to secure a stable procurement of their parts, the CF card connector has been changed.

The shape of the CF card connector has been partially changed. Changing the CF card connector does not affect the GOT functions.

1. Change details

The external appearance of the CF card connector has been changed.

Model	Before	After
GT1155-QTBD GT1155-QSBD GT1150-QLBD		
GT1155HS-QSBD GT1150HS-QLBD		
GT1665HS-VTBD*		

*:The position of the CF card access LED has moved from below the connector to the left of the connector.


2. How to check the target product.

The CF card connector has been changed for the GOT models with the hardware versions listed below.

Model	Hardware version	Serial number
GT1155-QTBD	F or later	152****~ (From February 2015)
GT1155-QSBD	N or later	152****~ (From February 2015)
GT1150-QLBD	J or later	152****~ (From February 2015)
GT1155HS-QSBD	M or later	153****~ (From March 2015)
GT1150HS-QLBD	E or later	153****~ (From March 2015)
GT1665HS-VTBD	H or later	159****~ (From September 2015)

Method for checking hardware version and serial number is shown below.

■ Indication on rating plate (GOT rear face)



REVISIONS

Version	Date of Issue	Revision
A	December 2014	First edition
B	January 2016	Added applicable model (GT1665HS-VTBD)