



技术简讯

[1 / 1]

FA-CN-0463-A

GX Works3的监视功能与梯形图程序的显示不更新时的处理方法

■出版年月

2025年7月

■相关机型

GX Works3

感谢您继续支持MELSOFT系列产品。

由于发生了GX Works3的监视功能与梯形图程序的显示不更新的事例，通知其现象与处理方法。

1 现象

受Windows®的功能影响，GX Works3的监视功能与梯形图程序的显示可能不更新。

三菱电机已确认使用Windows 11的以下功能时将发生本现象的事例。

- “Click to Do（单击以执行）”

2 处理方法

现象发生时的处理方法如下所示。

此外，根据所使用的操作系统与操作系统版本，菜单名与操作步骤可能不同。阅读时，应根据需要，按实际使用的操作系统与操作系统版本进行操作。

使用Windows的功能

在所使用的Windows中启用了以下功能时应将其禁用。

- “Click to Do（单击以执行）”

应在确认未使用该功能后再禁用功能。

操作步骤

- 选择Windows的开始⇒[Settings（设置）]⇒[Privacy & security（隐私和安全性）]⇒[Click to Do（单击以执行）]。

Windows不支持本功能时，不显示设置项目。

- 将“Click to Do（单击以执行）”设置为关闭。

修订记录

副编号	修订年月	修订内容
A	2025年7月	初版

商标

Microsoft and Windows are trademarks of the Microsoft group of companies.

The company names, system names and product names mentioned in this bulletin are either registered trademarks or trademarks of their respective companies.

In some cases, trademark symbols such as ™, ®, or ®, are not specified in this bulletin.

MITSUBISHI ELECTRIC CORPORATION

HEAD OFFICE: TOKYO BLDG., 2-7-3, MARUNOUCHI, CHIYODA-KU, TOKYO 100-8310, JAPAN
NAGOYA WORKS: 1-14, YADA-MINAMI 5-CHOME, HIGASHI-KU, NAGOYA 461-8670, JAPAN