


液晶テレビ受信不具合対象製品一覧表

形名
DSM-19L3
DSM-19L3-S
DSM-19L4
DSM-19L4-S
DSM-19L6
DSM-19L6-S
DSM-22L3
DSM-24L4
DSM-24L6
DSM-26L3
DSM-32L3
DSM-32L4
DSM-32L4-PW
DSM-32L6
DSM-40L3
DSM-40L4
DSM-40L4-PW
DSM-40L6
DSM-40L6(W)
DSM-50L3
DSM-50L4
DSM-50L4-PW
DSM-50L6
DSM-65L6

形名
LCD-19ATL40
LCD-19LB1
LCD-19LB10
LCD-19LB10DS
LCD-19LB3
LCD-19LB4
LCD-19LB6
LCD-19MX40
LCD-22LB1
LCD-22LB3
LCD-22ML1
LCD-22ML10
LCD-22MX40
LCD-22MX45
LCD-24LB4
LCD-24LB6
LCD-26BHR35
LCD-26LB3
LCD-26ML10
LCD-26MX45
LCD-26MX55
LCD-A26BHR3
LCD-G26BHR3
LCD-V26BHR3
LCD-29BW4
LCD-A29BHR4
LCD-V29BHR4
LCD-32BHR35
LCD-32BW6
LCD-32CB1
LCD-32CB2
LCD-32H5500X
LCD-32H5BX
LCD-32LB3
LCD-32LB4
LCD-32LB5
LCD-32LB6
LCD-32LB7
LCD-32LB6H
LCD-32ML1
LCD-32ML10
LCD-32ML10DS
LCD-32MR2
LCD-32MX40
LCD-32MX45
LCD-A32BHR3
LCD-A32BHR6
LCD-G32BHR3
LCD-V32BHR3
LCD-V32BHR6

形名
LCD-39BW4
LCD-39BW6
LCD-39LSR4
LCD-39LSR5
LCD-39LSR6
LCD-A39BHR4
LCD-A39BHR6
LCD-V39BHR4
LCD-V39BHR6
LCD-40BHR35
LCD-40CV6H
LCD-40DRW2
LCD-40DRW2-W
LCD-40MDR2
LCD-40MDR2Z
LCD-40MDR3
LCD-40ML3
LCD-40ML4
LCD-40ML6
LCD-40MLW1
LCD-40MLW2
LCD-40MXW400
LCD-A40BHR3
LCD-G40BHR3
LCD-V40BHR3
LCD-V40MDR3
LCD-46MDR2
LCD-46MDR3
LCD-V46MDR3
LCD-50CV6H
LCD-50LSR4
LCD-50LSR5
LCD-50LSR6
LCD-50MLW3
LCD-50MLW4
LCD-50MLW5
LCD-50MLW6H
LCD-55LSR3
LCD-55LSR3BK
LCD-55MDR2
LCD-58LS1
LCD-58LSR7
LCD-X58PR1
LCD-65LBW6H
LCD-65LS1
LCD-X65PR1



※3月29日(日)に公表した「お知らせ」の対象機種一覧表に誤りがありました。3機種(DSM-40L6(W)、LCD-19ATL40、LCD-32LB7)を追加し、1機種を削除しています。

※機種により表示位置が異なります。上記位置のいずれかに印刷、または、ラベル表示しております。
図示の矢印に示す場所は、概略の表示位置を示します。実際は、異なる場合があります。